




Feed screw

(by hex wrench 3)

Feed screw

(by hex wrench 3)



4-4.5 mounting hole,

7.5 deep counterbore